



















| | | | |
|---|--|---|--|
|  A great place to live, work & play | Scarborough Borough Council Condition Survey of Inclinometers and Piezometers – 10/4/2013 | |  Royal HaskoningDHV Enhancing Society Together |
| Location | Scarborough North Bay – Oasis Café | Towards the bottom of the footpath between the old and new Oasis Cafés. | |
| Borehole | BH2 | Piezometer (Automated) | |
| Map GPS Reference: TA 04008 89465 |  | | |
| Location Photo (looking north) |  | | |





| | | | | | |
|------------------------------|---|---------------------------|--|---------------|---------------|
| Condition Photos |  | |  | | |
| Condition | <ul style="list-style-type: none">• Cover ok, 4 locking screws in place.• In tarmac footpath.• Data logger present. | | | | |
| Recorded Depth to Instrument | Not available | | Recorded Depth to Water | Not available | |
| Known Depth to Instrument | 1.50m | Last Recorded Water Depth | Not available | Record Date | Not available |
| Comments | | | | | |



| | | | |
|---|--|--|--|
|  A great place to live, work & play | Scarborough Borough Council Condition Survey of Inclinometers and Piezometers – 10/4/2013 | |  Royal HaskoningDHV Enhancing Society Together |
| Location | Scarborough North Bay – Oasis Café | In footpath up the cliff, in second zig-zag from the bottom, heading towards the Clifton Hotel, at the bend in the path. | |
| Borehole | BH3p | Piezometer (Automated) | |
| Map GPS Reference: TA 04001 89448 |  | | |
| Location Photo (looking north-west) |  | | |





| | | | | | |
|------------------------------|--|---------------------------|--|-------------|---------------|
| Condition Photos |  | |  | | |
| Condition | <ul style="list-style-type: none">• Cover ok, 4 locking screws in place.• Concrete surround starting to break up.• Data logger present.• Half in tarmac footpath, and half in grass bank. | | | | |
| Recorded Depth to Instrument | | | Recorded Depth to Water | | |
| Known Depth to Instrument | 5.40m | Last Recorded Water Depth | Not available | Record Date | Not available |
| Comments | <ul style="list-style-type: none">• Just uphill from Borehole BH3 (inclinometer). | | | | |



| | | | |
|---|---|---|--|
| <div><p>A great place to live, work & play</p></div> | <div><p>Scarborough Borough Council</p><p>Condition Survey of Inclinometers and Piezometers – 10/4/2013</p></div> | | <div><p>Royal HaskoningDHV Enhancing Society Together</p></div> |
| <div><p>Location</p></div> | <div><p>Scarborough North Bay – Oasis Café</p></div> | <div><p>In footpath up the cliff, in second zig-zag from the bottom, heading towards the Clifton Hotel, just before the bend in the path.</p></div> | |
| <div><p>Borehole</p></div> | <div><p>BH3</p></div> | <div><p>Inclinometer</p></div> | |
| <div><p>Map</p><p>GPS Reference: TA 04003 89446</p></div> | <div></div> | | |
| <div><p>Location Photo</p><p>(looking north-west)</p></div> | <div></div> | | |

| | | | |
|------------------|--|----------------|-------|
| Condition Photos | <div></div> <div></div> | | |
| Condition | <ul style="list-style-type: none">• Cover and hinge ok, but locking screw is missing.• Concrete surround ok.• No cap to internal tube.• In tarmac footpath. | | |
| Known Depth | 6.00m | Recorded Depth | 5.87m |
| Comments | <ul style="list-style-type: none">• Water recorded at 0.8m.• Dummy inclinometer went to 5.87m.• Just downhill from Borehole BH3p. | | |

| | | | |
|---|--|---|--|
|  A great place to live, work & play | Scarborough Borough Council Condition Survey of Inclinometers and Piezometers – 10/4/2013 | |  Royal HaskoningDHV Enhancing Society Together |
| Location | Scarborough North Bay – Oasis Café | In footpath of Queen's Parade (at top of cliff), near the entrance to the cliff footpath, behind the 'Scarborough Fayre' hotel, close to the Clifton Hotel. | |
| Borehole | BH4p | Piezometer (Automated) | |
| Map GPS Reference: TA 03979 89431 |  | | |
| Location Photo (looking north-west) |  | | |

| | | | | | |
|------------------------------|---|---------------------------|--|---------------|---------------|
| Condition Photos |  | |  | | |
| Condition | <ul style="list-style-type: none">• Cover ok, 4 locking screws in place.• Data logger present.• In tarmac footpath. | | | | |
| Recorded Depth to Instrument | Not available | | Recorded Depth to Water | Not available | |
| Known Depth to Instrument | 13.10m | Last Recorded Water Depth | Not available | Record Date | Not available |
| Comments | <ul style="list-style-type: none">• Adjacent to BH4. | | | | |

| | | | |
|--|--|---|---|
|  <i>A great place to live, work & play</i> | Scarborough Borough Council Condition Survey of Inclinometers and Piezometers – 10/4/2013 | |  Royal HaskoningDHV <i>Enhancing Society Together</i> |
| Location | <i>Scarborough North Bay</i> – Oasis Café | In footpath of Queen’s Parade (at top of cliff), near the entrance to the cliff footpath, behind the ‘Scarborough Fayre’ hotel, close to the Clifton Hotel. | |
| Borehole | BH4 | Inclinometer | |
| Map GPS Reference: TA 03978 89434 |  | | |
| Location Photo (looking north-west) |  | | |

| | | | |
|------------------|--|----------------|--------|
| Condition Photos | <div></div> <div></div> | | |
| Condition | <ul style="list-style-type: none">• Cover ok, had been slightly tarmacked over but was still operational. Locking screw missing.• No cap to inner tube.• Outer tube full of water.• In tarmac footpath. | | |
| Known Depth | 14.00m | Recorded Depth | 13.90m |
| Comments | <ul style="list-style-type: none">• Water recorded at 13.4m.• Dummy inclinometer went to 13.90m.• Adjacent to BH4p. | | |