















<div><p>A great place to live, work &amp; play</p></div>	<div><p>Scarborough Borough Council</p><p>Condition Survey of Inclinometers and Piezometers – 9/4/2013</p></div>		<div><p>Royal HaskoningDHV Enhancing Society Together</p></div>
Location	Filey Town	At top of slipway, opposite the gift shop (next to amusement arcade), on the seaward side, close to the last lamppost.	
Borehole	CPBH03	Inclinometer	
Map	<div><p>GPS Reference: TA 12091 80915</p></div>		
Location Photo	<div><p>(looking south-east)</p><p>Last lamppost on the promenade before the slipway</p><p>Borehole CPBH03</p></div>		



<b>Condition Photos</b>			
<b>Condition</b>	<ul style="list-style-type: none"> <li>• Cover ok, but hinge very stiff.</li> <li>• Not locked, screw does not work.</li> <li>• No cap to inner tube.</li> <li>• In tarmac promenade – no vegetation issues.</li> </ul>		
<b>Known Depth</b>	10.00m	<b>Recorded Depth</b>	10.10m
<b>Comments</b>	<ul style="list-style-type: none"> <li>• Access restricted – boat was parked over the top.</li> <li>• Not enough space under boat to get dummy inclinometer down.</li> <li>• Water recorded at 0.35m.</li> </ul>		





 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclinometers and Piezometers – 9/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	On cliff top footpath (Cleveland Way) in southern section of Filey Brigg Country Park, between first and second benches, nearly in line with southern edge of car park.	
<b>Borehole</b>	CPBH02	<b>Piezometer – twin (Diver)</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 12063 81086			


Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover and hinge ok, painted red.</li><li>• Locked with screw.</li><li>• Concrete surround ok.</li><li>• Vegetation ok – mown grass, well maintained.</li></ul>				
Recorded Depth to Instrument	a) 34.4m b) 27.94m		Recorded Depth to Water	a) 30.80m b) dry	
Known Depth to Instrument	a) 34.40m b) 27.80m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Double piezometer with diver in pipe b (blue pipe).</li><li>• Diver length of 26.9m.</li></ul>				







 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclinoimeters and Piezometers – 9/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	In southern section of Filey Brigg Country Park, in scrubland along southern edge of mown grass area, in line with the corner of the red brick wall around graveyard.	
<b>Borehole</b>	CPBH04	<b>Piezometer – twin (Diver)</b>	
<b>Map</b>  GPS Reference: TA 12006 80952			
<b>Location Photo</b>  (looking west)			



Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover and hinges ok, locked with screw.</li><li>• Concrete surround ok.</li><li>• Located in scrub area, longer grass will be a problem in summer.</li></ul>				
Recorded Depth to Instrument	a) 29.85m b) 19.81m		Recorded Depth to Water	a)25.62m b) 19.58m	
Known Depth to Instrument	a) 30.00m b) 23.00m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Double piezometer with diver in pipe b (blue pipe).</li><li>• The nail from which the diver is suspended is at the side of the pipes, rather than across the top of pipe b due to space between top of pipe and borehole cover.</li><li>• Diver length of 19.47m.</li></ul>				


<div> A great place to live, work &amp; play</div>	<div>Scarborough Borough Council</div> <div>Condition Survey of Inclinometers and Piezometers – 9/4/2013</div>		<div> Royal HaskoningDHV Enhancing Society Together</div>
Location	Filey Town	In the corner of the field to the north of the road at the entrance to Filey Brigg Country Park. Opposite North Gate at Church Cliff Farm.	
Borehole	TP3	Piezometer	
Map	<div><div>GPS Reference: TA 11762 81223</div><div></div></div>		
Location Photo (looking east)	<div><div></div><div><div>Wellcome sign at entrance to country park</div><div>Locked access gate to field</div><div>Borehole TP3</div></div></div>		

Condition Photos			Cover padlocked (unable to access).			
Condition	<ul style="list-style-type: none"><li>• Raised tube – rusting, loose and at an angle (at edge of ploughed field, potentially hit by tractor).</li><li>• Concrete surround is broken.</li><li>• Protective fencing around the borehole is loose and damaged.</li><li>• Cover is padlocked (unable to access).</li><li>• Little vegetation growth, protective fencing highlights position of borehole.</li></ul>					
Recorded Depth to Instrument	Not available		Recorded Depth to Water		Not available	
Known Depth to Instrument	4.00m	Last Recorded Water Depth		Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Access to field is through a locked gate, presumably locked by farmer.</li></ul>					







<div><p>A great place to live, work &amp; play</p></div>	<div><p><b>Scarborough Borough Council</b></p><p><b>Condition Survey of Inclinometers and Piezometers – 9/4/2013</b></p></div>		<div><p><b>Royal HaskoningDHV</b> Enhancing Society Together</p></div>
<div><p><b>Location</b></p></div>	<div><p><i>Filey Town</i></p></div>	<div><p>In northern end of Filey Brigg Country Park, beyond the car park and café. In grassed area between the road (close to the final bend in the one way system) and fence line.</p></div>	
<div><p><b>Borehole</b></p></div>	<div><p>CPBH01</p></div>	<div><p><b>Piezometer – twin (Diver)</b></p></div>	
<div><p><b>Map</b></p><p><b>GPS Reference:</b> TA 12220 81432</p></div>	<div></div>		
<div><p><b>Location Photo</b></p><p>(looking west)</p></div>	<div></div>		


Condition Photos						
Condition	<ul style="list-style-type: none"><li>• Cover and hinge ok, painted red. Locked with screw.</li><li>• Concrete surround ok.</li><li>• Vegetation ok – mown grass, well maintained.</li></ul>					
Recorded Depth to Instrument	a) 20.68m b) 4.48m		Recorded Depth to Water	a) 19.88m b) 2.03m		
Known Depth to Instrument	a) 20.50m b) 4.80m	Last Recorded Water Depth	Not available	Record Date	Not available	
Comments	<ul style="list-style-type: none"><li>• Double piezometer with diver in pipe b (blue pipe).</li><li>• Diver length of 4.25m</li><li>• Outer tube full of water.</li></ul>					





 <i>A great place to live, work &amp; play</i>	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclonometers and Piezometers – 9/4/2013</b>		 <b>Royal HaskoningDHV</b> <i>Enhancing Society Together</i>
<b>Location</b>	<i>Filey Town</i>	In north-west (back) corner of field to the west of the nature reserve off Fir Tree drive.	
<b>Borehole</b>	BHB	<b>Piezometer</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 11045 81735			
<b>Location Photo</b>  (looking north-east)			
<b>Condition Photos</b>	Cover padlocked (unable to access)		



<b>Condition</b>	<ul style="list-style-type: none"> <li>• Raised tube.</li> <li>• Cover ok, padlocked (unable to access).</li> <li>• Protective fencing is loose.</li> <li>• Vegetation ok – scrub at edge of ploughed field, but tube is raised and protective fencing highlights location.</li> </ul>				
<b>Recorded Depth to Instrument</b>	Not available		<b>Recorded Depth to Water</b>	Not available	
<b>Known Depth to Instrument</b>	10.05m	<b>Last Recorded Water Depth</b>	Not available	<b>Record Date</b>	Not available
<b>Comments</b>	<ul style="list-style-type: none"> <li>• Access – track from A1039 Scarborough Road at western edge of housing (opposite Copse Hill), 250m up the track is access into south-west corner of adjacent field, there is then a gate into the required field in its south-west corner.</li> </ul>				







 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclonometers and Piezometers – 9/4/2013</b>		 Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	Halfway along southern boundary of field to east of nature reserve off Fir Tree Drive. Immediately behind No. 45 Wooldale Drive.	
<b>Borehole</b>	BHA	<b>Piezometer</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 11398 81529			
<b>Location Photo</b>  (Looking north-west)			



Condition Photos			Cover padlocked (unable to access).		
Condition	<ul style="list-style-type: none"><li>• Raised tube and cover in ok condition. Cover padlocked (unable to access).</li><li>• Protective fencing loose.</li><li>• Vegetation ok – in scrub at edge of ploughed field, but raised tube and protective fencing highlight location.</li></ul>				
Recorded Depth to Instrument	Not available		Recorded Depth to Water	Not available	
Known Depth to Instrument	10.00m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Access through fields from locked access gate at entrance to Filey Brigg Country Park (opposite North Gate of Church Cliff Farm), assumed that farmer has key.</li></ul>				





<div><p>A great place to live, work &amp; play</p></div>	<div><p>Scarborough Borough Council</p><p>Condition Survey of Inclinoimeters and Piezometers – 9/4/2013</p></div>		<div><p>Royal HaskoningDHV Enhancing Society Together</p></div>
<div><p>Location</p></div>	<div><p>Filey Town</p></div>	<div><p>In grassed area behind benches to the south-east of the wishing well in the park off The Crescent. Park entrance opposite Rutland Street.</p></div>	
<div><p>Borehole</p></div>	<div><p>CPBH06</p></div>	<div><p>Piezometer – twin (diver)</p></div>	
<div><p>Map</p><p>GPS Reference: TA 11883 80420</p></div>	<div></div>		
<div><p>Location Photo</p><p>(looking north-west)</p></div>	<div></div>		

Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover and hinge ok, locked with screw.</li><li>• Concrete surround ok.</li><li>• Vegetation ok – mown grass, well maintained.</li></ul>				
Recorded Depth to Instrument	a) 11.3m b) 20.8m		Recorded Depth to Water	a) 9.40m b) 10.88m	
Known Depth to Instrument	a) 29.50m b) 21.00m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Double piezometer with diver in pipe b (blue pipe).</li><li>• Diver has two instruments, one at ground level and the other at 15.5m.</li><li>• Piezometer pipes are low in the outer tube, measurements taken to top of outer tube.</li></ul>				





 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclinometers and Piezometers – 9/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	In grassed area on landward side of footpath, to the south of the dinosaur (Pleisosaur) sculpture and large shelter.	
<b>Borehole</b>	BH06	<b>Inclinometer</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 11904 80028			
<b>Location Photo</b>  (looking north)			





Condition Photos	<div></div> <div></div>		
Condition	<ul style="list-style-type: none"><li>• Cover ok but very rusted, hinge is very rusted and stiff.</li><li>• Locking screw present but rusted and no longer working.</li><li>• No cap present in internal tube.</li><li>• Slightly overgrown by grass but in well maintained mown grass area.</li></ul>		
Known Depth	30.00m	Recorded Depth	30.46m
Comments	<ul style="list-style-type: none"><li>• Water recorded at 8.68m.</li><li>• Dummy inclinometer went to 30.31m.</li><li>• Adjacent to Borehole CPBH08 – closer to footpath than BH06.</li></ul>		



<div> A great place to live, work &amp; play</div>	<div>Scarborough Borough Council</div> <div>Condition Survey of Inclinometers and Piezometers – 9/4/2013</div>		<div> Royal HaskoningDHV Enhancing Society Together</div>
Location	Filey Town	In grassed area on landward side of footpath, to the south of the dinosaur (Pleisosaur) sculpture and large shelter.	
Borehole	CPBH08	Piezometer – twin (diver)	
Map	<div></div>		
Location Photo (looking north)	<div></div>		








Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover ok but hinge does not open fully.</li><li>• Locking screw missing.</li><li>• Concrete surround ok.</li><li>• Vegetation ok – mown grass, well maintained.</li></ul>				
Recorded Depth to Instrument	a) 9.64m b) 24.1m		Recorded Depth to Water	a) dry b) 18.45m	
Known Depth to Instrument	a) 10.00m b) 23.90m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Double piezometer with diver in pipe a (blue pipe).</li><li>• Diver length of 9.3m.</li><li>• Piezometer pipes low down in outer tube, measurements taken to top of outer tube.</li><li>• Adjacent to BH06, but closer to the footpath.</li></ul>				







 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclinoimeters and Piezometers – 9/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	In triangle of scrubland between footpaths between pitch & putt and golf club. Closer to the more landward path.	
<b>Borehole</b>	CPBH09	<b>Piezometer – twin (diver)</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 11866 79834			
<b>Location Photo</b>  (looking south-west)			



Condition Photos						
Condition	<ul style="list-style-type: none"><li>• Cover and hinge ok, but no lock.</li><li>• Concrete surround ok.</li><li>• Long grass, likely to be difficult to locate in summer.</li></ul>					
Recorded Depth to Instrument	a) 29.53m b) 12.03m		Recorded Depth to Water	a) 9.56m b) 9.62m		
Known Depth to Instrument	a) 29.50m b) 12.40m	Last Recorded Water Depth	Not available	Record Date	Not available	
Comments	<ul style="list-style-type: none"><li>• Double piezometer with diver in pipe b (blue pipe).</li><li>• Diver length of 10.15m.</li></ul>					

 <p>A great place to live, work &amp; play</p>	<p><b>Scarborough Borough Council</b></p> <p><b>Condition Survey of Inclinometers and Piezometers – 10/4/2013</b></p>		 <p><b>Royal HaskoningDHV</b> Enhancing Society Together</p>
<p><b>Location</b></p>	<p><i>Filey Town</i></p>	<p>In grass verge between the road and promenade, close to Ackworth House (big white property).</p>	
<p><b>Borehole</b></p>	<p>CPBH05</p>	<p><b>Inclinometer</b></p>	
<p><b>Map</b></p> <p><b>GPS Reference:</b> TA 11977 80415</p>			
<p><b>Location Photo</b> (looking west)</p>			



Condition Photos	<div></div> <div></div>		
Condition	<ul style="list-style-type: none"><li>• Cover is ok apart from a broken corner where the lock should be. Hinge ok.</li><li>• Concrete surround ok.</li><li>• Vegetation ok – mown grass, well maintained.</li><li>• No cap present on inner tube.</li></ul>		
Known Depth	10.00m	Recorded Depth	10.09m
Comments	<ul style="list-style-type: none"><li>• Water at ground level, both inner and outer tube full.</li><li>• Dummy inclinometer went to 10.09m.</li></ul>		







 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclonometers and Piezometers – 10/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	In lower level pedestrian promenade at southern end of Filey seafront, in front of first set of beach chalets (most northern).	
<b>Borehole</b>	BH05B	<b>Piezometer</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 11954 80119			
<b>Location Photo</b>  (looking north-west)	 <div>Borehole BH05B</div>		



Condition Photos	<div></div> <div></div>					
Condition	<ul style="list-style-type: none"><li>• Cover and hinge ok, not locked as screw thread is damaged.</li><li>• Inside full of sand.</li><li>• Cap present on inner tube.</li><li>• In tarmac promenade.</li></ul>					
Recorded Depth to Instrument	6.34m		Recorded Depth to Water		6.15m	
Known Depth to Instrument	6.45m	Last Recorded Water Depth		6.05m	Record Date	2009 (Mouchel)
Comments	<ul style="list-style-type: none"><li>• Close to Borehole RCBH07 (located south of BH05B).</li><li>• SBC borehole lists this borehole as automated, but no equipment was found present.</li></ul>					





 <p>A great place to live, work &amp; play</p>	<p><b>Scarborough Borough Council</b></p> <p><b>Condition Survey of Inclinometers and Piezometers – 10/4/2013</b></p>		 <p><b>Royal HaskoningDHV</b> Enhancing Society Together</p>
<b>Location</b>	<i>Filey Town</i>	In lower level pedestrian promenade at southern end of Filey seafront, in front of Beach Superintendent's Office.	
<b>Borehole</b>	RCBH07	<b>Inclinometer</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 11956 80080			
<b>Location Photo</b>  (looking north)			

Condition Photos	<div></div> <div></div>		
Condition	<ul style="list-style-type: none"><li>• Cover and hinge ok.</li><li>• Thread inside locking mechanism stripped.</li><li>• Concrete surround ok.</li><li>• No cap to inner tube.</li><li>• In tarmac promenade.</li></ul>		
Known Depth	20.00m	Recorded Depth	20.22m
Comments	<ul style="list-style-type: none"><li>• Water recorded at 15.02m.</li><li>• Dummy inclinometer went to 20.22m.</li></ul>		





<div> A great place to live, work &amp; play</div>	<div>Scarborough Borough Council</div> <div>Condition Survey of Inclinometers and Piezometers – 10/4/2013</div>		<div> Enhancing Society Together</div>
Location	Filey Town	In grassed area in front of benches facing Filey Brigg, close to the park entrance near the White Lodge Hotel. Close to the yellow viewing telescope.	
Borehole	BH04	Piezometer	
Map	<div><div>GPS Reference: TA 11900 80126</div></div>		
Location Photo	<div><div>(looking south-west)</div><div>Borehole BH04</div></div>		





Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover has broken corner, and is not properly attached (broken hinge). Cover does not close properly.</li><li>• Some vegetation ingress under the cover.</li><li>• Vegetation ok – mown grass, well maintained.</li></ul>				
Recorded Depth to Instrument	9.25m		Recorded Depth to Water	2.99m	
Known Depth to Instrument	9.00m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Inner tube is low, measurements taken to top of outer tube.</li><li>• SBC lists this borehole as automate, but no equipment was present.</li></ul>				



 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclinoimeters and Piezometers – 10/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	Seaward side of cliff top footpath around the edge of the golf club, just past the gorse thicket directly on the footpath, and before the rise (heading southwards).	
<b>Borehole</b>	CPBH10	<b>Piezometer – twin (diver)</b>	
<b>Map</b>  <b>GPS Reference:</b> TA 11910 79583			
<b>Location Photo</b>  (looking south)			







Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover and hinge ok, locked with screw.</li><li>• Concrete surround ok.</li><li>• Wooden marker post with faded red paint – hard to spot from footpath.</li><li>• Long grass, would be difficult to locate in summer.</li></ul>				
Recorded Depth to Instrument	a) 12.05m b) 7.78m		Recorded Depth to Water	a) 12.03m b) 3.10m	
Known Depth to Instrument	a) 20.00m b) 8.10m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>• Double piezometer with diver in pipe b (blue pipe).</li><li>• Diver length of 5.4m.</li></ul>				





 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclinometers and Piezometers – 10/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	Filey Town	Behind goal posts in north-west corner of playing fields of Filey School (on A1039 Muston Road). Along the field boundary that borders the footpath.	
<b>Borehole</b>	TP8	<b>Piezometer</b>	
<b>Map</b>  GPS Reference: TA 10743 80345			
<b>Location Photo</b>  (looking north-west)			





Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover is broken with half missing, including locking mechanism.</li><li>• Hinge ok.</li><li>• Concrete surround ok.</li><li>• Cap on inner tube present but broken.</li><li>• Cover is raised up above playing field level – may have been broken when field is mown.</li><li>• Vegetation ok – mown playing field.</li></ul>				
Recorded Depth to Instrument	2.07m		Recorded Depth to Water	0.7m	
Known Depth to Instrument	4.00m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>•</li></ul>				








 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclonometers and Piezometers – 10/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	Field adjacent to Filey School playing field. Borehole is located towards the northern corner, along the north-east boundary, near where the wooded area steps back.	
<b>Borehole</b>	BHC	<b>Piezometer</b>	
<b>Map</b>  GPS Reference: TA 10603 80488	 <p>Map showing the location of the borehole BHC in Filey Town. The map includes Beacon Hill, Beacon Lodge, The Dams, and Filey School. A scale bar indicates 0 to 50 metres. The borehole BHC is marked with a purple triangle near Long Plantation.</p>		
<b>Location Photo</b>  (looking south-east)	 <p>Photograph of the borehole BHC location. The photo shows a grassy field with a wooded area in the background. An orange arrow points to the Filey School in the distance. Another orange arrow points to the borehole BHC in the foreground. A person is visible in the bottom right corner, kneeling and working with equipment.</p>		





Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Raised tube and cover ok, slight dent to outer tube.</li><li>• No lock or protective fencing.</li><li>• Concrete surround ok.</li><li>• Vegetation ok – short grass in field, might be grazed.</li></ul>				
Recorded Depth to Instrument	3.10m		Recorded Depth to Water	ground level	
Known Depth to Instrument	10.00m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>•</li></ul>				



 <i>A great place to live, work &amp; play</i>		<b>Scarborough Borough Council</b> <b>Condition Survey of Inclonometers and Piezometers – 10/4/2013</b>	 <b>Royal HaskoningDHV</b> <i>Enhancing Society Together</i>
<b>Location</b>	<i>Filey Town</i>	Playing field for Filey School (A1039 Muston Road), along south-west boundary close to the corner of the prefab classrooms.	
<b>Borehole</b>	TP9	<b>Piezometer</b>	
<b>Map</b>  GPS Reference: TA 10655 80115			
<b>Location Photo</b>  (looking south-east)	 <div>Borehole TP9</div>		




Condition Photos					
Condition	<ul style="list-style-type: none"><li>• Cover ok but rusted shut, hinge very stiff, and lock corroded.</li><li>• Concrete surround damaged and loose.</li><li>• Cap for inner tube present but was not on, it is degraded.</li><li>• Vegetation ok – mown playing field.</li></ul>				
Recorded Depth to Instrument	2.32m		Recorded Depth to Water	0.32m	
Known Depth to Instrument	4.00m	Last Recorded Water Depth	Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>•</li></ul>				

 A great place to live, work & play	<b>Scarborough Borough Council</b>			 <b>Royal HaskoningDHV</b> Enhancing Society Together	
<b>Location</b>	Filey Town		In footpath down the ravine at south side of Filey Town, leading from West Avenue to seafront.		
<b>Borehole</b>	BH02		<b>Piezometer</b>		
<b>Map</b>  <b>GPS Reference:</b> unknown					
<b>Location Photo</b>	Unable to locate				
<b>Condition Photos</b>	Unable to locate				
<b>Condition</b>	Unable to locate				
<b>Recorded Depth to Instrument</b>	Not available		<b>Recorded Depth to Water</b>	Not available	
<b>Known Depth to Instrument</b>	2.00m	<b>Last Recorded Water Depth</b>	0.56m	<b>Record Date</b>	2009 (Mouchel)
<b>Comments</b>	<ul style="list-style-type: none"><li>• Unable to locate – may have been tarmacked over when footpath was resurfaced.</li><li>• SBC confirmed borehole has been lost following site visit on 7/5/2013.</li><li>• Borehole BH02 to be removed from SBC monitoring programme.</li></ul>				

 A great place to live, work & play	<b>Scarborough Borough Council</b>  <b>Condition Survey of Inclinometers and Piezometers – 9/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	At northern edge of pitch & putt, close to top of steps from the ravine footpath.	
<b>Borehole</b>	BH01	<b>Piezometer (Automated)</b>	
<b>Map</b>  <b>GPS Reference:</b> unknown			
<b>Location Photo</b>  (looking west)			
<b>Condition Photos</b>			
<b>Condition</b>	• Unable to locate		



<b>Recorded Depth to Instrument</b>	Not available		<b>Recorded Depth to Water</b>	Not available	
<b>Known Depth to Instrument</b>	13.90m	<b>Last Recorded Water Depth</b>	13.00m	<b>Record Date</b>	2009 (Mouchel)
<b>Comments</b>	<ul style="list-style-type: none"> <li>• Unable to locate in scrub vegetation, may be possible to find with a metal detector.</li> <li>• SBC surveyed with metal detector on 7/5/2013 and confirmed borehole is lost. Likely to have been damaged and filled in by cutting activities at the putting green.</li> <li>• Borehole BH01 to be removed from SBC monitoring programme.</li> </ul>				

<div><p>A great place to live, work &amp; play</p></div>	<div><p>Scarborough Borough Council</p><p>Condition Survey of Inclonometers and Piezometers – 9/4/2013</p></div>		<div><p>Royal HaskoningDHV Enhancing Society Together</p></div>
Location	Filey Town	North-east corner of field to the west of track leading off the A1039 (Scarborough Road) opposite Copse Hill.	
Borehole	TP6	Piezometer	
Map	<div><div><p>ewbiggin West Farm</p><p>Newbiggin Gardens</p><p>Mill Hill</p><p>Crayke House Farm</p></div><div><p>Filey Field</p><p>TP6</p><p>Filey Fields Farm</p><p>East-Lea Farm</p></div><div><p>Parish Wood</p><p>PINEWOOD AVENUE</p><p>OAK CLOSE</p><p>ALMOND CLOSE</p><p>GROVE HILL ROAD</p><p>ELM C</p><p>THORN TREE AVENUE</p><p>ICE ROAD</p><p>WICKHAM AVENUE</p><p>CHERRY TREE DR</p><p>PLANT TREE WAY</p><p>SCARBOROUGH ROAD</p><p>ASH ST</p></div><div><p>0 50 Metres</p><p>Contains Ordnance Survey data © Crown copyright and database right 2013</p></div></div>		
Location Photo	<div><div><p>(looking south-west)</p></div><div></div></div>		
Condition Photos			

Condition	<ul style="list-style-type: none"><li>Unable to locate amongst overgrown vegetation and 'fly-tipping'. Possible pipe sticking up out of broken up concrete but it was raised above ground with no outer tube or cover. If this is the borehole then it is likely to have been significantly damaged.</li></ul>					
Recorded Depth to Instrument	3.60m		Recorded Depth to Water		0.57m	
Known Depth to Instrument	4.00m	Last Recorded Water Depth		Not available	Record Date	Not available
Comments	<ul style="list-style-type: none"><li>SBC surveyed on 7/5/2013 and confirmed pipe sticking out of fly-tipping is the borehole. It needs a new outer casing and protective fencing installing.</li></ul>					

 A great place to live, work & play	<b>Scarborough Borough Council</b> <b>Condition Survey of Inclinoimeters and Piezometers – 10/4/2013</b>		 <b>Royal HaskoningDHV</b> Enhancing Society Together
<b>Location</b>	<i>Filey Town</i>	In the field to the west of the car park on West Avenue.	
<b>Borehole</b>	BHD	<b>Piezometer</b>	
<b>Map</b>  <b>GPS Reference:</b> unknown			
<b>Location Photo</b>			
<b>Condition Photos</b>			
<b>Condition</b>	• Unable to locate		



<b>Recorded Depth to Instrument</b>	4.32m		<b>Recorded Depth to Water</b>	0.72m	
<b>Known Depth to Instrument</b>	10.00m	<b>Last Recorded Water Depth</b>	Not available	<b>Record Date</b>	Not available
<b>Comments</b>	<ul style="list-style-type: none"> <li>SBC located and surveyed on 7/5/2013. Condition of borehole and protective fencing ok. Depth and water recorded as above.</li> </ul>				