


Appendix A Figure 1 Site visit: Photo Locations



New features observed in 2014

- Ponded water
- Fluvial erosion
- Ridge
- Small cliff
- Tension cracks
- Valley

November 2014 Photo Locations

Previous (2005) mapping

Morphology

- cliff
- sharp break
- sharp concave
- sharp convex
- smooth break
- smooth concave
- smooth convex
- tension crack

Slope type

- smooth
- undulating

Geomorphological units

Feature

- active toe unloading
- back rotated block
- dormant toe unloading
- hillslopes of glacial deposits
- mudslide
- active oversteep headscarp
- lower slope landslide deposits
- translational slide
- seepage

0 20 40 60 80 100 Metres